



High Speed Precision Engine Lathe

Model: 2140GH~21120GH

Operational Manual

Taiwan : Taiwan Springwood Internation,Inc.

Formosa Springwood Internation,Inc.

No.101,506 Lane,Seng-Tso Road

Seng Karing Sharnng,Taichung County,Taiwan R.O.C

Tel : 886-4-2520-4120 Fax : 886-4-2520-4123

CA : Springwood Internation,Inc.

1062 N. Kraemer Place, Anaheim, CA92806 U.S.A

Tel : 714-632-9701 Fax : 714-632-9730

NJ : Klim Industrial,Inc.

244 N. Randolphville Rd. Piscataway, NJ 08854 U.S.A

Tel : 732-752-9100 Fax : 732-752-9101

Revised : 7/15/10

Table of Content

| Description | Page # |
|---|--------|
| 1. Safety Operation Rules | 2 |
| 2. Specifications | 4 |
| 3. Preparation of Operation | 5 |
| 4. Electric Circuit, Diagram & Breakdown of Electrical Components | 9 |
| 5. Operation | 15 |
| 6. Threading Chart | 20 |
| 7. Lubrication | 22 |
| 8. Trouble Cause & Trouble Shooting | 25 |
| 9. Mechanical Drawings & Parts Breakdown List | 26 |
| A. Headstock | 27 |
| B. Gear Train Assembly | 33 |
| C. Feed Gear Box | 34 |
| D. Apron | 39 |
| E. Carriage and Tool Post Assembly | 42 |
| F. Tailstock-regular | 45 |
| G. Steady Rest | 47 |
| H. Follow Rest | 49 |
| I. Taper Turning Attachment | 51 |

Important

Do not operate or repair the machine until you have read this manual thoroughly.

Do not operate or repair the machine until you have read appropriate manual!

Note: A safety manual must remain attached to the machine at all time.

SAFETY OPERATION RULES

1. Secure work! Using chuck to secure work piece whenever it is possible! It is safer than using operator's hand and it allows operator to freely operating the lathe using both hands.
2. Do not over-reach! Keep firm footing and balancing at all times.
3. Maintain tools with care! Keep cutting tools sharp and clean for the best and safest operation. Follow instructions for lubricating and changing accessories.
4. Disconnect tools! Before servicing, please make sure accessories such as cutting tools are disconnected.
5. Reduce the risk of unintentional start! Make sure power switch is in "off" position before intentionally plug-in.
6. Use only recommended accessories! Consult owner's manual for recommended accessories. Usage of improper accessories may increase risk and cause injury to operator.
7. Never stand on tool! Serious injury could occur if the tool or cutting tool is tipped or is unintentional contacted.
8. Check damage parts! Before further using cutting tool, guard or other part that is damaged should be carefully checked to determine that it will operate properly, perform its intended function, check for alignment of moving parts, binding of moving parts, breakage of parts, mounting and other conditions that may affect its operation. A guard or other part that is damaged should be replaced or repaired.
9. Never leave cutting tool running unattended. Please turn power off! Do not leave cutting tool until machine comes to a complete stop.
10. Always use safety gassed! Common eyeglasses only have impact resistant lenses. They are NOT safety glasses!
11. Keep guards in place! And keep them in working order.
12. Remove adjusting keys and wrenches! Form habit of double-checking keys and adjusting wrenches are removed from chuck before power on machine.
13. Keep work area clean! Cluttered areas will invite accidents.
14. Don't use power tools in dangerous environments! Do not use power tools in damp or wet location, or expose them to rain. Keep working area well lighted!
15. Keep children away! All visitors should be kept a safety distance from work area.
16. Make workshop child proof! With pad locks, master switches, or by removing starter keys.
17. Do not miss-use tool! Do not force tool or attachment to do a job for which it was not designed for!
18. Use proper tools! Proper tool will do the job better and safer at the rate which it is designed.

19. Wear proper apparels! No loose clothing, gloves, neckties, rings, bracelets, or other jewelry to get caught within machine moving parts. Nonslip footwear is recommended. Wear protective hair covering to contain long hair.
20. Never use machine in high speed over an hour.
21. Keep cutting tools in turning tight during operation!

SPECIFICATIONS

| Model | 2140GH | 2160GH | 2180GH | 21120GH |
|-----------------------------|---------------------------|--------|--------|---------|
| | 2540GH | 2560GH | 2580GH | 25120GH |
| Capacity | | | | |
| Center height | 270/315mm (10.63"/12.4") | | | |
| Max swing over bed | 540/630mm (21.26"/24.8") | | | |
| Max swing over gap | 720/810mm (28.35"/31.89") | | | |
| Max swing over cross slide | 360/450mm (14.17"/17.72") | | | |
| Distance between centers mm | 1000 | 1500 | 2000 | 3000 |
| inch | 39.37 | 59.06 | 78.74 | 118.11 |
| Main spindle | | | | |
| Spindle nose | D1-8 | | | |
| Spindle bore | 83mm/3.35" | | | |
| Spindle speeds | 25~1545RPM (18 steps) | | | |
| Carriage | | | | |
| Max slide travel | 330mm (13.2") | | | |
| Compound rest travel | 150mm (5.91") | | | |
| Tailstock | | | | |
| Tailstock spindle diameter | 75mm (2.95") | | | |
| Tailstock spindle travel | 170mm (6.69") | | | |
| Tailstock spindle taper | MT#5 | | | |
| Bed | | | | |
| Bed width | 350mm (13.78") | | | |
| Threading | | | | |
| Leadscrew | 4 TPI or 6mm/pitch | | | |
| Metric pitch threads | 0.5~7mm/pitch (24 kinds) | | | |
| Inch threads | 4~56 TPI (36 kinds) | | | |
| Module pitch threads | 0.25~3.5M (16 kinds) | | | |
| DP threads | 8~112 P (36 kinds) | | | |
| Feeding range | | | | |
| Range of longitudinal feeds | 0.06~0.88mm/rev. | | | |
| Range of cross feeds | 0.03~0.44mm/rev. | | | |
| Motor | | | | |
| Main spindle | 10/15HP (Opt.) | | | |
| Coolant pump | 1/8HP | | | |
| Net weight approx. | | | | |
| 21" series kgs | 2400 | 2700 | 3100 | 3200 |
| lbs | 5280 | 5940 | 6820 | 7040 |
| 25" series kgs | 2550 | 2820 | 3250 | 3350 |
| lbs | 5610 | 6204 | 7150 | 7370 |
| Gross weight approx. | | | | |
| 21" series kgs | 2700 | 3000 | 3400 | 3600 |
| lbs | 5940 | 6600 | 7480 | 7920 |
| 25" series kgs | 2850 | 3050 | 3550 | 3750 |
| lbs | 6270 | 6710 | 7810 | 8250 |

Preparation for operation

Notes before operation

Unpacking:

After unpacking the transportation wooden crate, please inspect the machine carefully. If there is any shortage or damage, please contact your local dealership immediately.

Moving & lifting

Moving & lifting the machine by using a special hang fixture as figure 1 (page 7) shown and insert the special hang fixture into the gap center of the machine bed. Raising and lowering the machine should be careful. Do not touch the leadscrew, spindle or handwheels, etc. Be careful; do not bump the machine against the floor! Before moving, please check the following areas:

1. Lock and clamp the tailstock.
2. Lock the saddle lock.
3. Engage half-nut with leadscrew.

Foundations:

Due to the cutting speed and spindle speed are much higher than before, an incomplete foundation will generate vibration and unstable cutting condition. Please have the foundation done as figure 2 (page 8) shown. Enough space and boundary are necessary. Machine should be installed at least three feet from the wall and other machines.

Leveling the machine:

Anchor bolts and installation blocks must be located steadily into the concrete mix. For alignment of the machine, please place the square precision level on the guideway of the bed (the preciseness of the level is 0.02/100mm or better) and measuring the level of the bed way from left to right, front to back and adjust the leveling bolts until the sensitivity is within 0.04/100mm.

After the leveling procedure is completed, please fasten the foundation nuts. If the flatness deviates when locking foundation nuts, then readjustment of the level is required. Please repeat the procedure until all nuts are tightened.

Clean up

Cosmoline was applied on the machine before transportation. For cleaning up the bed, slideways and leadscrews etc., we can use solvent such as WD 40 to clean off the cosmoline. Please do not use lacquer, varnish, or kerosene! Apply

lubrication oil to all the necessary areas. Check all the handles and levers to see if they are functioning normally, and then set them to neutral positions.

Electrical power connections:

Electrical cabinet is provided at the rear lower part of the headstock. In it, there is a panel with all the electrical components, transformers, and fuses, etc. We also provide the electrical diagram at following pages.

Cautions:

After power connection, please check spindle rotation, using the jogging switch and power on/off lever. If it rotates in counter-clockwise, the wiring is correct. If it is not, please switch two wire terminals at RST position. And then check the rotation again. Spindle rotation must be correct before machine operation.








Figure 1



| Model | B | C | D |
|-------|------|------|------|
| 18" | 1264 | 1355 | 1828 |
| 21" | 1302 | 1393 | 1866 |
| 25" | 1347 | 1438 | 1911 |


Unit : mm



| Model | A | A1 |
|----------------|------|------|
| 1840/2140/2540 | 1255 | 2190 |
| 1860/2160/2560 | 1755 | 2690 |
| 1880/2180/2580 | 2255 | 3190 |


Unit : mm

Figure 2




Electric Circuit, Diagram
&
Breakdown of Electrical
Components

ELECTRICAL CIRCUITING DIAGRAM (WITHOUT INVERTER)




ELECTRICAL CIRCUITING DIAGRAM (WITHOUT INVERTER)

2010-07-14-CE



ELECTRICAL CIRCUITING DIAGRAM (WITHOUT INVERTER) FOR CE ONLY




| Manufacturer | | SCHEDULE OF ELECTRICAL EQUIPMENT | | | Sheet | |
|---------------------|------------------------------------|--|---------------|-------------|---------------------|--|
| Order | | | | | | |
| TYPE LATHE MACHINE: | | | See also list | | Drawn | |
| | | | | | Checked | |
| Item | Description and function | Technical data | Quantity | Supplier | Suppliers reference | |
| QS | Main Power(Door lock) Switch | AC 600V/50HZ 3P 32A | 1 | C.H | CH-332 | |
| FU1 | AC FUSE | AC 600V | 1 | SHINING | FS-011 | |
| FU2 | TO TRANSFORMER | 30MM 3A | 1 | SHINING | FS-011 | |
| FU3 | AC Low Voltage to Transformer | AC 600v 30MM 5A | 1 | SHINING | FS-011 | |
| KM1 | Contactors (Option) | 3Pia Ri=AC660V Rt=25A | 1 | N.H.D | C-25D | |
| KM2 | | AC3 220V 2.2kW | 1 | | C-25D | |
| KM3 | | 380V 4.0kW | 1 | | C-12D10 | |
| KM4 | | Coil AC 24V | 1 | | C-12D10 | |
| KM1 | Auxiliary contacts | Ui=AC600V | 1 | N.H.D | CA1-D11 | |
| KM2 | | Ith=10A | 1 | | CA1-O11 | |
| FR1 | Over-Load (RealyS) (Option) | 15A | 1 | N.H.D | NTH | |
| FR2 | | 1.2A | 1 | | | |
| FR3 | | 0.5A | 1 | | | |
| KR | contactors-Realy | Coil=AC 24V AC 240V 5A DC 30V 5A | 1 | ARITY | MR-2P | |
| TC | Transformer | AC Hi=380V(220V) LO=24V 300VA | 1 | SUENN-LIANG | SP-TBS | |
| TB | Casset Terminal-Block | AC 600V MAX.20A AC 600V MAX.10A | 3 16 | SHINING | TA-020 TA-010 | |
| PL1 | Piolt-Lamps AC Power Lamp | AC 24V 1.5W 22 ϕ | 1 | MACK | MK/L-22 | |
| PL2 | Piolt-Lamps Pump Lamp | | 1 | | | |
| SB1 | Power Selector Switch | AC 250V 10A | 1 | MACK | MK/CF-22 | |
| SB4 | Emergency-Stop | MAX.600V | 1 | | MK/B-22 | |
| SB3 | Jogging-Botton | 1NO*1NC 22 ϕ | 1 | | MK/BF-22 | |
| SB2 | Pump-Selector | | 1 | | MK/C-22 | |
| LS4 | Safe-Cover | AC 125V 10A 250V 10A MAX.600V | 1 | MOUJEN | MJ-1701 | |
| LS2 | For-Limit.Switch | AC 125V 10A 250V 10A MAX.600V | 1 | MOUJEN | MJ-1704 | |
| LS3 | Rev-Limit.Switch | | 1 | | | |
| LS1 | Foot-Cut (L.s) | | 1 | | | |
| CABLE-LOCK | Cable-Glands | | 1 | AVG | M-16 | |
| LINE | Control-Line | 0.75mm ² MAX.300V (30/0.18)-7A Ambient Temp (35°C~60°C) | 1 | TONG-WU | | |
| CABLE | PVC Cable-Wire | 2.0mm ² *4c(37/0.26)16a 1.25mm ² *4c(50/0.18)11A Ambient Temp (35°C~60°C) MAX 600V | 1 | TONG-WU | | |

OPERATION

HEAVY DUTY / HIGH SPEED PRECISION LATHE (Conventional Type)

- | | | |
|---------------------------------------|-------------------------------------|----------------------------------|
| 1. Headstock | 14. Thread Cutting Engagement Lever | 28. Gap |
| 2. Feed Gear Box | 15. Threading Indicator Dial | 29. Feed Selector |
| 3. Tailstock | 16. Carriage Lock | 30. Auto Feed Clutch Lever |
| 4. Apron | 17. Lead Screw | 31. Starting Bar |
| 5. Spindle Speed Selector | 18. Feed Bar | 32. Feed Selector |
| 6. Hi, Middle & Low Speed Selector | 19. Spindle Control Lever | 33. Feed Selector |
| 7. Feed Direction Selector | 20. Quill Lock | 34. Feed Selector |
| 8. Feed Selector | 21. Coolant Pipe | 35. Engage Lever |
| 9. Oil Level Sight Window | 22. Jogging Switches | 36. Hand Oiler |
| 10. EMG. Stop Switches | 23. Brake Pedal | 37. Pressure Adjusting Screw |
| 11. Longitudinal Transverse Handwheel | 24. Power Switches | 38. Longitudinal Kick-out Device |
| 12. Cross Feed Handle | 25. Coolant Pump Switches | 39. Stopping Bar |
| 13. Longitudinal Cross Feed Selector | 26. Foundation Bolts | 40. Carriage Lock Capscrew |
| | 27. Quill Transverse Handwheel | |



SPINDLE SPEED SELECTION, STOP & RE-START : (Conventional Type)

The first turn on the power source switch and then, set the feed direction selecting lever (7) at neutral position, set the spindle speed change lever (5) to the desired speed rate and set the hi-low speed selecting lever (6) to either high or low position, after that, move the spindle start lever (19) upward or downward which will caused the spindle rotates in counter – clockwise or in clockwise direction. (Speed selecting can be referred as Graph 2)

As for to stop the spindle rotation which can be employed your foot leg to foot pedal the foot pedal brake (23).

After the spindle stopped by foot pedal brake and want to restart the spindle rotation, the spindle start lever should be pushed to the neutral position first, and then, followed by the selection of forward / reverse direction.

CAUTIONS

- If want to change the spindle speed which must be stopped the spindle rotating, otherwise, the gear of headstock will be damaged.
- If it is hard to set the lever on position when making speed change, we can push the jogging switch (22) slightly and then, set the selecting lever again.

HOW TO OPERATE THE JOGGING SWITCH


During in operating, if we want to make speed change more easier or adjusting the center for chucking raw material when four jaws chuck is used and then, we can employ couple with the jogging switch (22).

GEAR CHANGE SYSTEM


The gear change system is located at the left side of the headstock as fig shown, please refer to thread cutting as Graph 1.

CAUTIONS

- Don't attempt to change gears when the spindle is running.



Graph 1



Graph2

HOW TO OPERATE THE CARRIAGE & APRON:

For longitudinal feed push down the longitudinal-cross feed selector ⑬, But for cross feed, which will pull up the selector ⑬ and refer table 2)。

MANUAL FEED:

Carriage moves longitudinally by turn the longitudinal traverse handwheel ⑪, meanwhile, set the feed direction selecting lever ⑦ the thread cutting engaging lever ⑭ at neutral position and pull up the long-cross feed selector ⑬ up (one graduation of handwheel dial is corresponding to 0.002" and one turn also corresponding to 0.4" travel of carriage.)


AUTO FEED:

The auto feed is operated as following procedures:

1. Select the feed direction by feed direction selecting lever ⑦
2. Set gear change and shift levers ⑧ & ⑩ to desired feed rate
3. Shift auto feed clutch lever ⑬ to feed direction
4. Pull the thread cutting engaging lever ⑭ up
5. Turn the longitudinal-cross selecting lever to either longitudinal or cross feed position
6. Shift the spindle start lever ⑱ to forward direction
7. When the auto feed clutch lever ⑬ shifted and the auto feed will be processed. But the auto feed clutch lever ⑬ is shifted to the neutral position and the feed will be stopped followingly.

SWIVELLING THE TOOL POST:

If want making swivelling the tool post which must loosen tool carriage lock capscrew ④ before.



| LEVER | | Ⓢ MM Feed speed. | | | | | | | | |
|-------|---|------------------|------|------|------|------|------|------|------|------|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| C | A | 0.50 | 0.57 | 0.63 | 0.69 | 0.70 | 0.73 | 0.76 | 0.82 | 0.89 |
| | B | 0.25 | 0.28 | 0.31 | 0.34 | 0.35 | 0.36 | 0.38 | 0.41 | 0.44 |
| D | A | 0.12 | 0.14 | 0.15 | 0.17 | 0.17 | 0.18 | 0.19 | 0.20 | 0.22 |
| | B | 0.06 | 0.07 | 0.08 | 0.08 | 0.08 | 0.09 | 0.09 | 0.10 | 0.11 |

Table 2

HOW TO OPERATE THE TAILSTOCK:

There is a center fixed in the sleeve of MT#5 and aligned with the center-line of the headstock. The sleeve can be moved by rotating the handwheel. One graduation of handwheel dial is corresponding to 0.002" and one turn also corresponding to 0.2" travel of tailstock spindle, the total range of movement of the sleeve is 150mm.

In order to accommodate to the length of the workpiece, the tailstock can slide along the bed way by pushing or pulling it to the required position and then, locked it by lifting the tailstock clamp lever up till tighten.

THREADING CHART

| LEVER | | W FOR CUTTING INCH THREAD | | | | | | | | |
|-------|---|-----------------------------|------|------|-------|------|------|------|------|-------|
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| D | A | 4 | 4½ | 4¾ | 5 | 5½ | 5¾ | 6 | 6½ | 7 |
| | B | 8 | 9 | 9½ | 10 | 11 | 11½ | 12 | 13 | 14 |
| C | A | 16 | 18 | 19 | 20 | 22 | 23 | 24 | 26 | 28 |
| | B | 32 | 36 | 38 | 40 | 44 | 46 | 48 | 52 | 56 |
| LEVER | | M FOR CUTTING METRIC THREAD | | | | | | | | |
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| C | A | 4 | 4.5 | 4.75 | 5 | 5.5 | 5.75 | 6 | 6.5 | 7 |
| | B | 2 | 2.25 | | 2.5 | 2.75 | | 3 | 3.25 | 3.5 |
| D | A | 1 | | | 1.25 | | | 1.5 | | 1.75 |
| | B | 0.5 | | | 0.625 | | | 0.75 | | 0.875 |
| LEVER | | W FOR CUTTING D.P. THREAD | | | | | | | | |
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| D | A | 8 | 9 | 9½ | 10 | 11 | 11½ | 12 | 13 | 14 |
| | B | 16 | 18 | 19 | 20 | 22 | 23 | 24 | 26 | 28 |
| C | A | 32 | 36 | 38 | 40 | 44 | 46 | 48 | 52 | 56 |
| | B | 64 | 72 | 76 | 80 | 88 | 92 | 96 | 104 | 112 |
| LEVER | | M FOR CUTTING MODULE THREAD | | | | | | | | |
| | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
| C | A | 2 | 2.25 | | 2.5 | 2.75 | | 3 | 3.25 | 3.5 |
| | B | 1 | | | 1.25 | | | 1.5 | | 1.75 |
| D | A | 0.5 | | | 0.625 | | | 0.75 | | 0.875 |
| | B | 0.25 | | | | | | | | |

HOW TO OPERATE THE LEADSCREW:

When shift the feed direction selecting lever ⑦ to the right or left and so as to the leadscrew will run forward or reverse rotating respectively.

INCH THREAD SYSTEM:

The inch thread cutting is operated as following procedures:

1. The gear change are aligned for ready making inch threading cutting.
2. Thus, shift levers ⑧, ⑩, ⑫ to the desired position and shift lever to one of 8 position.
3. Shift spindle start lever ⑬ downward to the forward rotating direction.
4. Shift thread cutting engaging lever down (half nut engaged) to start thread cutting.

THREAD CUTTING INDEXING:

The thread cutting indexing is installed on the headstock panel which has eight graduation. For making inch thread cutting. the thread cutting indexing will be prepared to correct position of half nut engaging quickly and conveniently.

As for the metric thread cutting, the half nut should be engaged with lead screw completely (when the leadscrew is in inch)

Which let tool post back to start position by spindle reversing rotating and then, feeding engaging again, when making metric thread cutting using leadscrew of imperial system or vice versa, the thread cutting engaging lever has to maintain engaged until to the end of thread cutting process.

LUBRICATION

LUBRICATION IN HEADSTOCK & FEED GEAR BOX:

Those are oil bath lubricated for both gear box and headstock, please always beware the oil level is not lower than the minimum level of oil window.

LUBRICATION IN GEAR CHANGE SYSTEM:

Open the protecting cover of gear change system and dip the lubricating oil with drop oiler daily.

LUBRICATION IN CARRIAGE & TOOL POST:

Carriage slides lubricated by hand oil pump and the tool post lubricated with drop oiler daily before starting the machine.

LUBRICATION IN APRON:




The apron itself is served as an oil reservoir, it's rotating parts are dipped into the oil bath, and the other parts are lubricated by splashing. Be sure the oil on proper height of oil window.







LUBRICATION IN BEDWAY, LEADSCREW, & LEADSCREW POST:


The bed way, leadscrew and leadscrew post which must lubricated with drop oiler oftenly due to operating condition.

FLUID COOLANT FOR CUTTING:

The coolant pump will be employed when the machining work is running and push on the coolant pump switch ④.

| | | | |
|------------------|---|---|---|
| |  |  |  |
| Service Interval | Daily | When required | Up oil level Window oftenly |

| | | |
|---|---|--|
|  |  |  |
|  |  |  |



TROUBLE CAUSE & TROUBLE SHOOTING


| TROUBLE ITEM | CAUSE | REMEADY |
|---|--|--|
| Vibration | Loose levelling screws Torn or mismatched Vee belts Work or chuck out of balance operating at high spindle speed. Motor out of balance | Set all screws so they bear evenly on leveling plates. Replace vee belts with matched set, or adjust roll. Balance chuck or reduce spindle speed. Contact local representative or motor manufacturer. |
| Chatter | Tool bit improperly ground or not on center Tool overhang too great Using improper surface feet Feed rate too high or too low Gibs of cross slide or pound rest loose Spindle bearings worn | Regrind tool bit or adjust tool holder so that area of contact between tool bit and work is decreased. Avoid extreme negative rake angle. Keep point of tool bit as close as possible to tool holder. Reduce or increase spindle speed. Reduce or increase feed. adjust gibs. Adjust spindle bearings. |
| Chatter (cont'd) | Work Improperly supported Vibration Spindle bearing loose | Adjust tailstock center. Use steady rest or follow rest on long slender shafts. Minimize tailstock barrel extension. See "Vibration" trouble above. Adjust spindle bearings. |
| Work not turned straight | Headstock and tailstock centers not aligned Work improperly supported Bed not level Tool not on center when using taper attachment | Align tailstock center Use steady rest or follow rest. Reduce overhang from chuck. Relevel bed, using precision level. Put tool on center. |
| Work out or round | Work loose between centers or centers are excessively worn--work centers out of round Loose headstock spindle bearings | Adjust tailstock center, regrind centers. Lap work centers. Adjust headstock spindle bearings. |
| Cross slide or compound rest movement does not coincide with dial movement of respective adjusting screw. | Gib setting too tight or too loose Workpiece is too long and slender | Adjust gibs. Use steady rest or follow rest. |

Mechanical Drawings & Parts Breakdown List




Note: When ordering parts, please be prepared with,

1. Machine model & serial number.
2. Item number.
3. Part number and description.
4. Year of Production.
5. Voltage & horsepower.
6. Quantity

HEADSTOCK (WITHOUT INVERTER)



Headstock



HEADSTOCK (WITHOUT INVERTER)

| SERIAL NO. | PARTS No. | DESCRIPTION | Q'TY |
|------------|-----------|--------------|------|
| 1 | 25HA-001 | Headstock | 1 |
| 2 | 25HA-002 | Cover | 1 |
| 3 | 25HA-003 | Spindle | 1 |
| 4 | 25HA-004 | Shaft | 1 |
| 5 | 25HA-005 | V-Pulley | 1 |
| 6 | 25HA-006 | Cover | 1 |
| 7 | 25HA-007 | Spur Gear | 1 |
| 8 | 25HA-008 | Spur Gear | 1 |
| 9 | 25HA-009 | Spur Gear | 1 |
| 10 | 25HA-010 | Keyway Shaft | 1 |
| 11 | 25HA-011 | Spur Gear | 1 |
| 12 | 25HA-012 | Spur Gear | 1 |
| 13 | 25HA-013 | Spur Gear | 1 |
| 14 | 25HA-014 | Spur Gear | 1 |
| 15 | 25HA-015 | Spur Gear | 1 |
| 16 | 25HA-016 | Spur Gear | 1 |
| 17 | 25HA-017 | Spur Gear | 1 |
| 18 | 25HA-018 | Spur Gear | 1 |
| 19 | 25HA-019 | Keyway Shaft | 1 |
| 20 | | | |
| 21 | 25HA-021 | Spur Gear | 1 |
| 22 | 25HA-022 | Spur Gear | 1 |
| 23 | 25HA-023 | | 1 |
| 24 | 25HA-024 | | 1 |
| 25 | 25HA-025 | | 1 |
| 26 | 25HA-026 | Shaft | 1 |
| 27 | 25HA-027 | Spur Gear | 1 |
| 28 | 25HA-028 | Shaft | 1 |
| 29 | | | |
| 30 | 25HA-030 | Spur Gear | 1 |
| 31 | 25HA-031 | Spur Gear | 1 |
| 32 | 25HA-032 | Keyway Shaft | 1 |
| 33 | 25HA-033 | Spur Gear | 1 |
| 34 | 25HA-034 | Spur Gear | 1 |
| 35 | 25HA-035 | Master Nut | 1 |
| 36 | 25HA-036 | Spacer Ring | 1 |
| 37 | 25HA-037 | Snap Cover | 1 |
| 38 | 25HA-038 | Snap Cover | 1 |
| 39 | 25HA-039 | Snap Cover | 1 |
| 40 | 25HA-040 | Snap Cover | 1 |

| SERIAL NO. | PARTS No. | DESCRIPTION | Q'TY |
|------------|-----------|--------------------|------|
| 41 | | | |
| 42 | 25HA-042 | Snap Cover | 1 |
| 43 | 25HA-043 | Cam Shaft | 1 |
| 44 | 25HA-044 | Cam | 1 |
| 45 | 25HA-045 | Speed Change Fork | 1 |
| 46 | 25HA-046 | Cam | 1 |
| 47 | 25HA-047 | Speed Change Fork | 1 |
| 48 | 25HA-048 | Counter-Sink Screw | 2 |
| 49 | 25HA-049 | Worm Gear | 1 |
| 50 | 25HA-050 | Pinion Shaft | 1 |
| 51 | 25HA-051 | Worm Gear | 1 |
| 52 | | | |
| 53 | 25HA-053 | Spur Gear | 1 |
| 54 | 25HA-053 | Spur Gear | 1 |
| 55 | 25HA-053 | Spur Gear | 1 |
| 56 | 25HA-056 | Locking Post | 1 |
| 57 | 25HA-057 | Shaft | 1 |
| 58 | 25HA-058 | Snap Cover | 1 |
| 59 | | | |
| 60 | 25HA-060 | Lever Boss | 1 |
| 61 | 25HA-061 | Rocker Arm | 1 |
| 62 | 25HA-062 | Snap Cover | 1 |
| 63 | 25HA-063 | Shaft | 1 |
| 64 | 25HA-064 | Lever Boss | 1 |
| 65 | 25HA-065 | Speed Change Fork | 1 |
| 66 | 25HA-066 | Speed Change Fork | 1 |
| 67 | 25HA-067 | Rocker Arm | 1 |
| 68 | 25HA-068 | Lever Boss | 1 |
| 69 | 25HA-069 | Handle | 2 |
| 70 | 25HA-070 | Shaft | 1 |
| 71 | 25HA-071 | Shaft | 1 |
| 72 | 25HA-072 | Speed Change Fork | 2 |
| 73 | 25HA-073 | Sleeve | 1 |
| 74 | | | 1 |
| 75 | | | 1 |
| 76 | | | 1 |
| 77 | | | 1 |
| 78 | | | 1 |
| 79 | | | 1 |
| 80 | | | 1 |


| SERIAL NO. | PARTS No. | DESCRIPTION | Q'TY |
|------------|-----------|------------------------|------|
| 81 | | | |
| 82 | | | |
| 83 | | | |
| 84 | | | |
| 85 | 25HA-085 | Key (8×7×29) | 1 |
| 86 | 25HA-086 | Bearings (6206ZZ) | 1 |
| 87 | 25HA-087 | Screw (CAP6×30) | 7 |
| 88 | 25HA-088 | Oil Seal (45×30×8) | 1 |
| 89 | 25HA-089 | Oil Ring (P65) | 4 |
| 90 | 25HA-090 | Bearings (6207) | 7 |
| 91 | 25HA-091 | Key (8×7×128) | 2 |
| 92 | 25HA-092 | Screw (M8×25) | 1 |
| 93 | 25HA-093 | Pump | 1 |
| 94 | 25HA-094 | Bearings (6306) | 1 |
| 95 | 25HA-095 | Bearings (6206) | 4 |
| 96 | 25HA-096 | Key (8×7×30) | 2 |
| 97 | 25HA-097 | C Locker (S50) | 1 |
| 98 | 25HA-098 | C Locker (S55) | 1 |
| 99 | 25HA-099 | Key (8×7×35) | 2 |
| 100 | 25HA-100 | O Ring (P55) | 3 |
| 101 | 25HA-101 | Key (10×7×76) | 2 |
| 102 | 25HA-102 | C Locker (s52) | 1 |
| 103 | 25HA-103 | C Locker (S35) | 1 |
| 104 | 25HA-104 | C Locker (S50) | 1 |
| 105 | 25HA-105 | O Ring (G115) | 1 |
| 106 | 25HA-106 | Bearings (6020Z) | 1 |
| 107 | 25HA-107 | Key (10×8×70) | 4 |
| 108 | 25HA-108 | Screw (Cap6×25) | 15 |
| 109 | 25HA-109 | O Ring (P170) | 1 |
| 110 | 25HA-110 | Bearings (32021/32022) | 2 |
| 111 | 25HA-111 | C Locker (R47) | 2 |
| 112 | 25HA-112 | O Ring (P25) | 1 |
| 113 | 25HA-113 | Bearings (6005) | 3 |
| 114 | 25HA-114 | Bearings (6305) | 1 |
| 115 | 25HA-115 | Key (8×7×18) | 2 |
| 116 | | | |
| 117 | 25HA-117 | Key (8×7×30) | 1 |
| 118 | 25HA-118 | Screw (Cap6×35) | 3 |
| 119 | 25HA-119 | Oil Seal (38×25×8) | 1 |
| 120 | 25HA-120 | Bearings (6205) | 3 |

| SERIAL NO. | PARTS No. | DESCRIPTION | Q'TY |
|------------|-----------|--------------------|------|
| 121 | 25HA-121 | Key(6×6×10) | 2 |
| 122 | 25HA-122 | C Locker (S45) | 1 |
| 123 | 25HA-123 | Screw (M10×15) | 9 |
| 124 | 25HA-124 | Key (6×6×30) | 1 |
| 125 | 25HA-125 | C Locker (S20) | 1 |
| 126 | 25HA-126 | Screw (M6×P10) | 2 |
| 127 | | | |
| 128 | 25HA-128 | Key (8×7×25) | 2 |
| 129 | 25HA-129 | C Locker (S20) | 1 |
| 130 | 25HA-130 | Screw (Cap M6×1) | 3 |
| 131 | 25HA-131 | (M10×10) | 1 |
| 132 | 25HA-132 | (φ8×30) | 1 |
| 133 | 25HA-133 | Steel Ball (φ8) | 1 |
| 134 | 25HA-134 | Oil Seal (38×25×8) | 1 |
| 135 | 25HA-135 | Screw (Cap M8×25) | 3 |
| 136 | 25HA-136 | Oil Seal (P40) | 1 |
| 137 | 25HA-137 | Oil Seal (38×22×8) | 1 |
| 138 | 25HA-138 | Spring Pin (φ6×70) | 1 |

GEAR TRAIN FOR 21" SERIES



METRIC UNITS




IMPERIAL UNITS



GEAR TRAIN FOR 21" SERIES, SPINDLE BORE 85MM (3")

| NO. | PARTS NO. | DESCRIPTION | Q'TY | REMARK |
|-----|-------------|--|------|--------|
| 01 | 25HA-081000 | GEAR 42T, M2.5 | 1 | |
| 02 | 25HA-082000 | GEAR 56T, M2.5 | 1 | |
| 03 | 18HA-080000 | SAFE PIN BASE | 1 | |
| 04 | 16B-031000 | GEAR 28T, M1.75 | 1 | |
| 05 | 20B-033000 | HAVING TWO LAYERS END GEAR 128T, M1.75 HAVING TWO LAYERS END GEAR 120T, M1.75 | 1 | |
| 06 | 20B-038A00 | BRACKET | 1 | |
| 07 | 20B-037000 | SHAFT | 1 | |
| 08 | 20B-036000 | SHAFT | 1 | |
| 09 | 20B-035000 | END GEAR 42T, M1.75 | 1 | |
| 10 | 20B-034000 | END GEAR 49T, M1.75 | 1 | |
| 11 | | BEARING 6005 | 2 | |
| 12 | | C LOCKER R47 | 2 | |
| 13 | | C LOCKER S25 | 1 | |
| 14 | | SPRING WASHER M16 | 1 | |
| 15 | | NUT M16 | 1 | |

Feed Gear Box



Feed Gear Box





| NO. | PARTS NO. | DESCRIPTION | Q'TY | REMARK |
|------|------------|-------------------------------|------|-----------|
| 01 | 20G-001000 | GEAR BOX BODY | 1 | |
| 02 | 20G-002000 | FRONT COVER | 1 | |
| 03-1 | 20G-003100 | GEAR | 1 | |
| 03-2 | 20G-003200 | SLEEVE | 1 | |
| 04 | 20G-004000 | SHAFT | 1 | |
| 06 | 20G-006000 | CLUTCH | 1 | |
| 07 | 20G-007000 | SHAFT | 1 | (SECOND) |
| 008 | 20G-008000 | GEAR OF CLUTCH | 1 | |
| 09 | 20G-009000 | COLLAR | 1 | |
| 12 | 20G-012000 | GEAR | 1 | |
| 13 | 20G-013000 | SHAFT | 1 | (THIRD) |
| 14 | 20G-014000 | GEAR | 1 | |
| 15 | 20G-015000 | CLUTCH | 1 | |
| 16 | 20G-016000 | GEAR OF CLUTCH | 1 | |
| 17 | 20G-017000 | GEAR OF CLUTCH | 1 | |
| 18 | 20G-018000 | SHAFT | 1 | (FOUR) |
| 19 | 20G-019000 | GEAR | 1 | NINE STEP |
| 20 | 20G-020000 | GEAR | 1 | NINE STEP |
| 21 | 20G-021000 | GEAR | 1 | NINE STEP |
| 22 | 20G-022000 | GEAR | 1 | NINE STEP |
| 23 | 20G-023000 | GEAR | 1 | NINE STEP |
| 24 | 20G-024000 | GEAR | 1 | NINE STEP |
| 25 | 20G-025000 | GEAR | 1 | NINE STEP |
| 26 | 25G-026000 | GEAR | 1 | NINE STEP |
| 27 | 20G-027000 | GEAR | 1 | |
| 28 | 20G-028000 | SHAFT | 1 | |
| 29 | 20G-029000 | GEAR | 1 | |
| 30 | 20G-030000 | SHELF OF ROCKER ARM / HOUSING | 1 | |
| 31 | 20G-031000 | SHAFT | 1 | |
| 32 | 20G-032000 | GEAR | 1 | |
| 34 | 20G-034000 | SHIFT FORK | 1 | |
| 35 | 20G-035000 | FEED SHAFT | 1 | |
| 36 | 20G-036000 | MIDDLE SHAFT | 1 | |
| 38 | 20G-038000 | LEAD SCREW SHAFT | 1 | |
| 39 | 20G-039000 | GEAR | 1 | |
| 40 | 20G-040000 | COUPLING SOCKET | 1 | |
| 41 | 20G-041000 | NUT | 1 | |
| 51 | 20G-051000 | COVER | 1 | |

| NO. | PARTS NO. | DESCRIPTION | Q'TY | REMARK |
|-----|-------------|--------------------------|------|--------|
| 52 | 20G-052000 | STUFF | 1 | |
| 54 | 20G-054000 | COVER | 1 | |
| 60 | 20G-060000 | SHAFT | 1 | |
| 62 | 20G-062000 | CHANGE SPEED SHIFT BLOCK | 1 | |
| 63 | 20G-063000 | CHANGE SPEED SHIFT BLOCK | 2 | |
| 65 | 20G-065000 | CHANGE SPEED SHIFT FORK | 3 | |
| 66 | 20G-066000 | CHANGE SPEED SHIFT FORK | 3 | |
| 68 | 20G-068000 | ROCKER | 3 | |
| 70 | 20G-070000 | SETTING PLATE | 1 | |
| 71 | 20G-071000 | SHIFT SHAFT | 1 | |
| 72 | 20G-072000 | SHIFT FORK | 1 | |
| 73 | 20G-073000 | SHIFT RACK | 1 | |
| 74 | 20G-074000 | SHIFT PIN | 1 | |
| 75 | 20G-075000 | SLIDE WEDGE | 1 | |
| 76 | 20G-076000 | SLIDE WEDGE | 1 | |
| 78 | 20G-078000 | TURNTABLE GEAR | 1 | |
| 79 | 20G-079000 | SHELF / HOUSING | 1 | |
| 80 | 20G-080000 | SHAFT BASE | 1 | |
| 81 | 20G-081000 | SHORT PILLAR | 1 | |
| 82 | 20G-082000 | COVER | 1 | |
| 83 | 20G-083000 | SPEED CHANGE DISC | 1 | |
| 84 | 20G-084000 | ROCKING LEVER | 1 | |
| 85 | 18HA-068000 | SPEED CHANGE LINK BASE | 3 | |
| 86 | 18HA-069000 | SPEED CHANGE SHAFT | 3 | |
| 87 | 20B-017000 | SHORT SHAFT | 1 | |
| 88 | 20B-034000 | GEAR | 1 | |
| 101 | | BEARING 6001 | 2 | |
| 102 | | BEARING 6003 | 1 | |
| 103 | | BEARING 6004 | 3 | |
| 104 | | BEARING 6005 | 2 | |
| 105 | | BEARING 6203 | 1 | |
| 106 | | BEARING 6204 | 1 | |
| 107 | | BEARING 6205 | 1 | |
| 108 | | BEARING 6905ZZ | 1 | |
| 109 | | BEARING 51105 | 1 | |
| 110 | | BEARING TA1725 | 1 | |
| 111 | | BEARING HK1812 | 1 | |
| 112 | | BEARING HK2220 | 1 | |
| 113 | | BEARING HK2520 | 1 | |

| NO. | PARTS NO. | DESCRIPTION | Q'TY | REMARK |
|-----|-----------|------------------------|------|--------|
| 114 | | BEARING TA3530 | 1 | |
| 115 | | C LOCKER S15 | 1 | |
| 116 | | C LOCKER S22 | 1 | |
| 117 | | C LOCKER S25 | 1 | |
| 118 | | C LOCKER S35 | 2 | |
| 119 | | C LOCKER S45 | 2 | |
| 120 | | O RING G30 | 1 | |
| 121 | | O RING G35 | 2 | |
| 122 | | O RING G45 | 1 | |
| 123 | | O RING G55 | 1 | |
| 124 | | O RING G85 | 1 | |
| 125 | | O RING P11 | 1 | |
| 126 | | OIL SEAL 40*55*8 | 1 | |
| 127 | | OIL SEAL 48*62*8 | 1 | |
| 128 | | KEY 5*5*20 | 1 | |
| 129 | | KEY 6*6*10 | 1 | |
| 130 | | KEY 6*6*12 | 1 | |
| 131 | | KEY 6*6*14 | 1 | |
| 132 | | KEY 6*6*25 | 1 | |
| 133 | | KEY 6*6*95 | 1 | |
| 134 | | CAP SCREW M6*10 | 2 | |
| 135 | | CAP SCREW M6*12 | 5 | |
| 136 | | CAP SCREW M6*20 | 4 | |
| 137 | | CAP SCREW M6*30 | 16 | |
| 138 | | CAP SCREW M8*14 | 1 | |
| 139 | | CAP SCREW M8*30 | 3 | |
| 140 | | SEMICIRCLE SCREW M5*10 | 4 | |
| 141 | | SEMICIRCLE SCREW M6*20 | 6 | |
| 142 | | SETSCREW M6*6 | 1 | |
| 143 | | SETSCREW M8*8 | 5 | |
| 144 | | SETSCREW M8*10 | 1 | |
| 145 | | SETSCREW M8*16 | 1 | |
| 146 | | SETSCREW M8*20 | 3 | |
| 147 | | SPACER | 1 | |
| 148 | | NUT M16 | 1 | |
| 149 | | SPRING SPACER M16 | 1 | |
| 150 | | SPRING DIA.6MM | 6 | |
| 151 | | STEEL BALL DIA.6MM | 6 | |

Apron





APRON

| SERIAL NO. | PARTS NO. | DESCRIPTION | Q'TY |
|------------|-----------|------------------|------|
| 1 | 20A-001 | Apron Body | 1 |
| 2 | 20A-002 | Cover | 1 |
| 3 | 20A-003 | Cover | 1 |
| 4 | 20A-004 | Shaft | 1 |
| 5 | 20A-005 | Graduated Collar | 1 |
| 6 | 20A-006 | Housing | 1 |
| 7 | 20A-007 | Pinion Shaft | 1 |
| 8 | 20A-008 | Spur Gear | 1 |
| 9 | 20A-009 | Housing | 1 |
| 10 | 20A-010 | Handwheel | 1 |
| 11 | 20A-011 | Handle Grip | 2 |
| 12 | 20A-012 | Lever Boss | 2 |
| 13 | 20A-013 | Shaft | 2 |
| 15 | 20A-015 | Gear | 1 |
| 16 | 20A-016 | Shaft | 1 |
| 17 | 20A-017 | Shaft | 1 |
| 18 | 20A-018 | Housing | 1 |
| 19 | 20A-019 | Housing | 1 |
| 20 | 20A-020 | Worm Gear | 1 |
| 21 | 20A-021 | Gear | 1 |
| 22 | 20A-022 | Shaft | 1 |
| 23 | 20A-023 | Shaft | 1 |
| 24 | 20A-024 | Shaft | 1 |
| 25 | 20A-025 | Half Nut Support | 1 |
| 26 | 20A-026 | Half Nut | 1 |
| 27 | 20A-027 | Gib | 1 |
| 28 | 20A-028 | Gear | 1 |
| 29 | 20A-029 | Axle | 1 |
| 30 | 20A-030 | Bush | 1 |
| 31 | 20A-031 | Bush | 1 |
| 32 | 20A-032 | Gear | 1 |
| 33 | 20A-033 | Worm Box | 1 |
| 34 | 20A-034 | Baffle | 1 |
| 35 | 20A-035 | Shaft Gear | 1 |
| 36 | 20A-036 | Collar | 1 |
| 37 | 20A-037 | Housing | 1 |
| 38 | 20A-038 | Shaft | 1 |
| 39 | 20A-039 | Rocking Arm | 1 |
| 40 | 20A-040 | Safety Block | 1 |
| 41 | 20A-041 | Stick Bar | 1 |

| | | | |
|----|---------|----------------------|---|
| 42 | 20A-042 | Housing | 1 |
| 43 | 20A-043 | Shaft | 1 |
| 45 | 20A-045 | Hand Knob | 1 |
| 48 | | Bearing 51104 | 1 |
| 49 | 20A-049 | Lock Nut | 1 |
| 54 | 20A-054 | Oil Seal (30×40×5) | 1 |
| 55 | 20A-055 | Thrust Bearing 51103 | 2 |
| 56 | 20A-056 | Bearing 6005 | 1 |
| 58 | 20A-058 | Bearing 6004 | 2 |

Carriage & Tool Post




CARRIAGE AND TOOL POST

| SERIAL NO. | PARTS NO. | DESCRIPTION | Q'TY |
|------------|-----------|------------------------|------|
| 1 | 20S-001 | Carriage | 1 |
| 2 | 20S-002 | Cross Slide | 1 |
| 3 | 20S-003 | Plate | 1 |
| 4 | 20S-004 | Lock Gib | 1 |
| 5 | 20S-005 | Plate | 2 |
| 6 | 20S-006 | Lock Plate | 1 |
| 7 | 20S-007 | Screw | 1 |
| 8 | 20S-008 | Nut | 1 |
| 9 | 20S-009 | Gear | 1 |
| 10 | 20S-010 | Gib | 1 |
| 11 | 20S-011 | Bracket | 1 |
| 12 | 20S-012 | Screw Boss | 1 |
| 13 | 20S-013 | Lock Nut | 1 |
| 14 | 20S-014 | Screw | 1 |
| 15 | 20S-015 | Graduated Collar | 1 |
| 16 | 20S-016 | Nut | 2 |
| 17 | 20S-017 | Handle | 1 |
| 18 | 20S-018 | Handle Grip | 1 |
| 19 | 20S-019 | Gear | 1 |
| 20 | 20S-020 | Shaft | 1 |
| 21 | 20S-021 | Nut | 2 |
| 22 | 20S-022 | Bracket | 1 |
| 23 | 20S-023 | Lock Screw | 1 |
| 24 | 20S-024 | Adjusting Bolt For Gib | 2 |
| 25 | 20S-025 | Wiper | 1 |
| 26 | 20S-026 | Plate | 1 |
| 27 | 20S-027 | Wiper | 2 |
| 28 | 20S-028 | Plate | 2 |
| 29 | 20S-029 | Wiper | 2 |
| 30 | 20S-030 | Plate | 2 |
| 33 | 20S-033 | Screw | 1 |
| 34 | 20S-034 | Plate | 1 |
| 35 | 20S-035 | Set Screw M8×25 | 1 |
| 36 | 20S-036 | Key | 1 |
| 37 | 20S-037 | Cap Screws M8×25 | 3 |
| 38 | 20S-038 | Cap Screws M10×35 | 2 |
| 39 | 20S-039 | Spring Pin ϕ 5×28 | 1 |
| 40 | 20S-040 | Thrust Bearing 51103 | 1 |
| 41 | 20S-041 | Oiler ϕ 1/4" | 1 |
| 42 | 20S-042 | Spring ϕ 1/4" | 2 |

| SERIAL NO. | PARTS NO. | DESCRIPTION | Q'TY |
|------------|-----------|--|------|
| 43 | 20S-043 | Steel Ball ϕ 1/4" | 2 |
| 44 | 20S-044 | Cap Screws M8 \times 20 | 5 |
| 45 | 20S-045 | Nuts M8 | 5 |
| 46 | 20S-046 | Set Screws M8 \times 30 | 5 |
| 47 | 20S-047 | Cap Screws M8 \times 16 | 4 |
| 48 | 20S-048 | Snap Screws S13 | 1 |
| 49 | 20S-049 | Set Screws M6 \times 6 | 1 |
| 50 | 20S-050 | Key 4 \times 4 \times 25 | 1 |
| 51 | 20S-051 | Thrust Bearing 51103 | 1 |
| 52 | 20S-052 | Clamping Bolt | 1 |
| 53 | 20S-053 | Hcnolle Boss | 1 |
| 54 | 20S-054 | Seven | 1 |
| 55 | 20S-055 | Thrust Bearing 51104 | 1 |
| 56 | 20S-056 | Washer | 1 |
| 57 | 20S-057 | Hex. Set Screw | 3 |
| 58 | 20S-058 | Turret Tool Post | 1 |
| 59 | 20S-059 | Pin | 3 |
| 60 | 20S-060 | Sleeve | 1 |
| 61 | 20S-061 | Locking Block | 1 |
| 62 | 20S-062 | Gib | 1 |
| 63 | 20S-063 | Cam Screw | 1 |
| 64 | 20S-064 | Sacating Screw | 12 |
| 65 | 20S-065 | Screw | 3 |
| 66 | 20S-066 | Pin | 1 |
| 67 | 20S-067 | Spring ϕ .5/12 | 1 |
| 68 | 20S-068 | Steel Ball ϕ 3/16" | 1 |
| 69 | 20S-069 | Spring ϕ 3/16" | 1 |
| 70 | 20S-070 | Hex. Set Screw M6 \times 91 \times 61 | 1 |
| 71 | 20S-071 | Wasker | 1 |
| 72 | 20S-072 | Key | 1 |
| 73 | 20S-073 | Nut | 1 |
| 74 | 20S-074 | Lever | 1 |
| 75 | 20S-075 | Indexing Base | 1 |
| 76 | 20S-076 | Indexing Ring | 1 |
| 77 | 20S-077 | Bracket | 1 |
| 78 | 20S-078 | Thrust Bearing 51102 | 2 |
| 79 | 20S-079 | Locking Screw 20S-079 | 1 |
| 80 | 20S-080 | Nut M6 \times P1 | 1 |
| 81 | 20S-081 | Hex. Set Screw M6 \times P1 \times 201 | |
| 82 | 20S-082 | Screw Nut | 1 |
| 83 | 20S-083 | Adjusting Screw | 1 |
| 84 | 20S-084 | Gib | 1 |
| 85 | 20S-085 | Cover | 1 |
| 86 | 20S-086 | Tool Slide | 1 |
| 87 | 20S-087 | Ailer | 2 |

| SERIAL NO. | PARTS NO. | DESCRIPTION | Q'TY |
|------------|-----------|----------------------|------|
| 1 | 20T-001 | Tailstock | 1 |
| 2 | 20T-002 | Tailstock Base | 1 |
| 3 | 20T-003 | Quill | 1 |
| 4 | 20T-004 | Screw | 1 |
| 5 | 20T-005 | Nut | 1 |
| 6 | 20T-006 | Bracket | 1 |
| 7 | 20T-007 | Dial | 1 |
| 8 | 20T-008 | Nipping Stud | 1 |
| 9 | 20T-009 | Nipping Bush | 1 |
| 11 | 20T-011 | Eccentric Lock Stud | 1 |
| 12 | 20T-012 | Locking Lever | 1 |
| 13 | 20T-013 | Clamping Bolt | 1 |
| 14 | 20T-014 | Clamping Bolt | 1 |
| 15 | 20T-015 | Holding Down Plate | 1 |
| 16 | 20T-016 | Stop Pin | 1 |
| 17 | 20T-017 | Nipping Nut | 1 |
| 18 | 20T-018 | Locking Handle | 1 |
| 19 | 20T-019 | Key | 1 |
| 20 | 20T-020 | Center | 1 |
| 21 | 20T-021 | Oil Seal (58×72×9) | 1 |
| 22 | 20T-022 | Oiler | 1 |
| 23 | 20T-023 | Cap Screws | 3 |
| 24 | 20T-024 | Thrust Bearing 51104 | 2 |
| 25 | 20A-010 | HandWheel | 1 |
| 26 | 20T-026 | Key | 1 |
| 27 | 20A-057 | Handle | 1 |
| 28 | 20T-028 | Cap Screws | 4 |
| 29 | 20T-029 | Spring | 1 |
| 30 | 20T-030 | Steel Ball | 1 |
| 31 | 20T-031 | Washer | 1 |
| 32 | 20T-032 | Nut | 1 |
| 33 | 20T-033 | Nut | 1 |
| 34 | 20T-034 | Washer | 1 |
| 35 | 20T-035 | Cap Screw | 2 |
| 36 | 20T-036 | Steel Ball | 1 |
| 37 | 20T-037 | Spring | 1 |
| 38 | 20T-038 | Set Screw | 1 |
| 39 | 20T-039 | Set Screw | 1 |
| 40 | 20T-040 | Plate | 2 |
| 41 | 20T-041 | Wiper | 2 |
| 42 | 20T-042 | Screw | 8 |
| 43 | 20T-043 | Plate | 2 |
| 44 | 20T-044 | Wiper | 2 |


Steady Rest



Steady Rest

| Serial No. | Part No. | Description | Q'ty |
|------------|------------|---------------------------|------|
| 1 | 21SR-001 | Steady rest housing-top | 1 |
| 1-1 | 21SR-002 | Steady rest housing-lower | 1 |
| 2 | 21SR-003 | Roller shaft | 3 |
| 3 | 21SR-004 | Shaft roller | 3 |
| 4 | 21SR-005 | Adjusting knob | 3 |
| 5 | 21SR-006 | Housings tighten knob | 1 |
| 6 | 21SR-007 | Shaft locating screw | 3 |
| 7 | 21SR-008 | Housings connecting screw | 1 |
| 8 | 25T-015100 | Locating plate | 1 |
| 9 | | Square head cap screw | 1 |
| 10 | | Square washer | 1 |
| 11 | | Hex nut | 1 |
| 12 | 21SR-009 | Adjusting shaft | 1 |





Follow Rest



Follow Rest

| Serial No. | Part No. | Description | Q'ty |
|-------------------|-----------------|-----------------------|-------------|
| 1 | 21FR-001 | Follow rest housing | 1 |
| 2 | 21FR-002 | Shaft with brass tip | 2 |
| 3 | 21FR-003 | Adjust knob | 2 |
| 4 | 21FR-004 | Shaft screw | 2 |
| 5 | | Socket head cap screw | 2 |
| 6 | | Washer | 2 |
| 7 | | Socket head set screw | 2 |

Taper Turning Attachment



Taper Turning Attachment

| Serial No. | Part No. | Description | Q'ty |
|------------|----------|------------------------------|------|
| 1 | 21TA-001 | Taper attachment body | 1 |
| 2 | 21TA-002 | Gib-taper turning attachment | 1 |
| 3 | 21TA-003 | Top slide casting | 1 |
| 4 | 21TA-004 | Sliding body | 1 |
| 5 | 21TA-005 | Socket head cap screw | 2 |
| 6 | 21TA-006 | Rotating/sliding plate | 1 |
| 7 | 21TA-007 | Top cover | 1 |
| 8 | 21TA-008 | Round head cap screw + | 4 |
| 9 | 21TA-009 | Locating plate | 1 |
| 10 | 21TA-010 | Screw with knob | 1 |
| 11 | 21TA-011 | Socket head cap screw | 2 |
| 12 | 21TA-012 | Socket head cap screw | 1 |
| 13 | 21TA-013 | Connecting shaft | 1 |
| 14 | 21TA-014 | Connecting bracket | 1 |
| 15 | 21TA-015 | Socket head cap screw | 1 |
| 16 | 21TA-016 | Socket cap set screw | 2 |
| 17 | 21TA-017 | Dual side connecting shaft | 1 |
| 18 | 21TA-018 | Socket cap set screw | 2 |
| 19 | 21TA-019 | Shaft locating bracket | 1 |
| 20 | 21TA-020 | Socket head cap screw | 2 |
| 21 | 21TA-021 | Socket cap set screw | 1 |
| 22 | 21TA-022 | Hex nut | 2 |
| 23 | 21TA-023 | Gib screw-taper attachment | 2 |
| 24 | 21TA-024 | Socket head cap screw | 4 |
| 25 | 21TA-025 | Screw connecting bracket | 1 |
| 26 | 21TA-026 | Socket head cap screw | 1 |
| 27 | 21TA-027 | Sleeve | 1 |
| 28 | 21TA-028 | Connecting plate | 1 |
| 29 | 21TA-029 | Plate | 1 |
| 30 | 21TA-030 | Gib | 1 |