


1.8Cordless Brushless Impact Driver

ADPL04-8/DCPL04-8/KDPL04-8



2022-09-02

No	Code	Name of Spare Parts	Remark
1	30021600033	Retaining Ring For Shaft 12	
2	30021600173	Washer 7 (12×15×0.5)	
3	30024500066	Compression Spring (13.2×0.7×15)	
4	30029902734	Chuck Cover	
5	30021000010	Steel Ball 3.5	
6	30010000602	Rubber Sleeve	
8	30010300264	O Ring	
10	30016300038	Nylon Washer	
11	30020100261	Drive Spindle	
12	30029902704	Impact Block	
13	30020500137	Planet Gear	
14	30029900178	Pin	
15	30021600103	Washer (18×12.5×1)	
16	30020500134	Annular Gear	
17	30010300019	O Ring (38×2)	
18	30021400197	Ball Bearing 61801 2RS	
19	30019901954	Rear Cover Of Gearbox	
21	30021400234	Ball Bearing 295	
23	30100300036	Stator	
23	30200300021	Stator	
23	30500300013	Stator	
23	30400300019	Stator	
24	30015500046	Rear Cover (Blue)	
24	30015500053	Rear Cover (Green)	
24	30015500052	Rear Cover (Red)	
25	30021200062	Cross Recessed Pan Head Tapping Screw ST2.9×16	
26	30019901940	Reversing Switch Lever (Red)	
26	30019902034	Reversing Switch Lever (Black)	
27	30030100404	Signal Switch	
27	30030100423	Signal Switch (JIABENBT-EP)	
28	30019900109	Terminal Block	
33	30029902703	Hook	
34	30021100680	Cross Recessed Pan Head Screw M2.5×7.5	
37	30024000220	Clamping Plate	
38		Battery Pack	
39		Battery Charger	
T1	30009801193	Front Housing Of Gearbox Assembly	Including: 7、9
T2	30100200032	Armature Assembly	Including: 20-22
T2	30200200029	Armature Assembly	Including: 20-22

T2	30500200020	Armature Assembly	Including: 20-22
T2	30400200029	Armature Assembly	Including: 20-22
T3	30009801195	PCBA	Including: 29、30
T4	30115410248	Motor Housing Assembly (东成)	Including: 35、36
T4	30415400255	Motor Housing Assembly (DongCheng)	Including: 35、36
T4	30215410245	Motor Housing Assembly (DCA)	Including: 35、36
T4	30515400251	Motor Housing Assembly (DCK)	Including: 35、36