




PART LIST FOR DIAGRAM OF MC1018

PART NO.	DESCRIPTION	QTY
1	Bed	1
2	Semicircle head screw	2
3	Retaining plate	1
4	Handwheel	1
5	Tailstock	1
6	Lock lever	1
7	Eccentric axis	1
8	Tail axis	1
9	Taper rod	1
10	Bearing ball	1
11	Cup center	1
12	Headstock spur center	1
13	Faceplate	1
14	Headstock spindle	1
15	Bearing ball	1
16	Ring retaining	1
17	Ring retaining	1
18	Bearing ball	1
19	Headstock	1
20	Back lid	1
21	Screw	3
22	Balance wheel	1
23	Side plate	1
24	Hex. socket set screw	1
25	Drive pulley	1
26	Drive belt	1
27	Hex. socket head screw M8×25	5
28	Hex. socket set screw M6×10	1
29	Motor pulley	1

30	Hex. socket head screw	3
31	Motor plate	1
32	Motor	1
33	Lock lever	1
34	Ring retaining 12	2
35	Tool rest	1
36	Tool rest base	1
37	Bolt	1
38	Lock plate	1
39	Hex. nut	1
40	Lock handle for knife base	1
41	Lock lever	1
42	Bolt	1
43	Lock plate	1
44	Hex. nut	1
45	Power cord	1
46	Plate	1
46-1	Washer	2
46-2	Screw	2
47	Switch	1
48	Washer	4
49	Spring washer	8
50	Rubber washer	4
51	Switch box	1
52	Washer	4
53	Ring retaining 10	1
54	Tailstock quill	1
55	Bolt	1
56	Handle	1
57	Moving knob	2
58	Stationary knob	2

59	Extension bed	1
60	Plate	1
61	Screw	2
62	Cover	1