


WOOD LATHE PARTS DIAGRAM



WOOD LATHE PARTS LIST

NO.	DESCRIPTION	Q'TY	NO.	DESCRIPTION	Q'TY
1	HEADSTOCK	1	43	CLAMP-A	1
2	FACE PLATE	1	44	HEX NUT	3
3	HEADSTOCK SPUR	1	45	ANGULAR SETTING ASSEMBLY	1
4	SPINDLE	1	46	SCREW	2
5	KEY	1	47	SPRING WASHER	2
6	BEARING	2	48	GEAR ASSEMBLY	1
7	"C"RING	2	49	SPEED LABEL	1
8	SPRING	1	50	INSTRUCTION MANUAL	1
9	BRACKET-SHIFTING LEVER	1	51	HEX SCREW	3
10	"C"RING	1	52	BACK	1
11	"C"RING	1	53	BOLT-B	2
			54	CLAMP-B	2
13	MOTOR	1	55	ECCENTRIC ROD	1
14	KEY	1	56	TOOL REST BODY	1
15	SCREW	1	57	HANDLE ASSEMBLY	2
16	COVER-MOTOR	1	58	EXTENSION TOOL REST	1
17	PULLEY-MOTOR(RIGHT & LEFT)	1	59	LOCK HANDLE-TAILSTOCK	1
			60	TOOL REST	1
19	SPRING	1	61	TAILSTOCK SPUR	1
20	SLEEVE	1	62	TAIL SPINDLE	1
21	"C"RING	2	63	TAIL STOCK SCREW	1
22	PUSH-OUT ROD	1	64	HANDLE ASSEMBLY	1
23	KNOB	2	65	TAILSTOCK	1
24	"C"RING	3	66	WASHER	1
25	ECCENTRIC ROD	1	67	HANDLE WHEEL	1
26	SCREW	1	68	SCREW	1
27	"C"RING	1	69	SCREW	1
28	PULLEY-SPINDLE(LEFT & RIGHT)	1	70	STAND UPPER COVER	2
29	V-BELT	1	71	STAND LEG, LEFT	2
			72	STAND LEG, RIGHT	2
31	BEARING	1	73	PLATE	1
32	NUT-LOCK	1	74	SWITCH	1
33	NUT	9	75	SWITCH BOX	1
34	CLAMP	2	76	POWER CORD	1
35	NUT M4x40	2	77	CARRIAGE BOLT M8 x 12	20
36	"C"RING	1	78	WASHER 8MM	20
37	TURNING BASE	1	79	WASHER 8MM	8
38	BED	1	80		
39	BAFFLE	2	81	COVER	1
40	SCREW	4	82	PLASTIC JAM NUT M20 X 1.5	1
41	HEX WRENCH	4	83	Screw	2
42	BOLT-A	1	84		