



No.22 Honghu W. Road, New North district, Chongqing, China www.toholift.com









## MILL TEST CERTIFICATE

Certificate Number: TC230714001

Location of Issue: Shangding Industry Park, No.22 Honghu West Road, New North District, Chongqing, China

Description of Product: G80 Alloy Chain Sling, Four Leg

Item No.	chain size(mm) x length(m)	0°-45°(T)	45 °-60 °(T)	Result	
1	13MMX1M	11.4	8	OK	

## Accessories testing

		chain 13mm		master link 13mm		clevis hook 13mm		connecting link13-8	
	Item No.	Working Load Limit (T)	Proof Load (Kn)	Working Load Limit (T)	Proof Load (Kn)	Working Load Limit (T)	Proof Load (Kn)	Working Load Limit (T)	Proof Load (Kn)
	1	5	128	5.3	132	5.3	132	5.3	132

ALL THE INSPECTIONS COMPLIED WITH THE QUALITY STANDARDS.

 $\textbf{Note:} \ \ \textbf{Meets the performance requirements of } \ \ \textbf{Specification EN818-2 for chain, EN1677 for hook.}$ 

except for those provisions required of the contractor.

Has not been contaminated by Mercury in the manufacturing process.

Comments: Minimum ultimate strength is 4 times the WLL

Certificate based on item being the TOHO product described above

Product Delivered To: CAPRIS S.A.

July 14,2023

Date of Issuance

Signature (Inspector)

TOHO Quality Assurance Manager